

1. unzip the file and transfer to a USB driver
2. insert USB driver to AN-1201T2 sample and power on 1201T2
3. click update in main menu and run the update
4. after update,pls reboot the stb